

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-14-0140-070	359 Whiskey Springs Road	2010	W005474	new tank
40-25-0060-026A	461 Petersburg Road	2009	W005473	lowering tanks only
40-10-0634-036	202 Heisers Lane	2009	W005472	new tank
40-11-0286-087	511 Park Drive	2009	W005471	new tank
40-23-0585-011	1660 Trindle Road	2009	W005468	new at-grade bed
40-42-3277-004A	559 Meals Road	2009	W005467	new tank
40-37-2540-004	644 Baltimore Pike	2009	W005465	ex. System malfunction - holding tanks
40-09-0527-019	50 Baker Drive	2009	W005463	new tank
40-43-2759-020	898 Goodyear Road	2009	W005444	holding tank - future sand mound
40-39-2211-001	230 Oxford Road	2009	W005462	no system designed - failed perc tests
40-11-0284-023	373 Mountain Road	2009	W005461	new system
40-09-0529-022	201 Marsh Drive	2009	W005456	eco-flo with at-grade bed (replaces ex. Bed)
40-10-0634-051	306 Bonnybrook Road	2008	W005442	New Sand Mound
40-40-2652-011	205 Frost Road	2008	W005439	2 dwellings on one lot
40-10-0636-067	498 Petersburg Road	2008	W005437	new tank
40-11-0286-090	919 Petersburg Road	2008	W005432	malfunction - indentified by on-lot management program
40-11-0288-005	162 E. Old York Road	2008	W005428	new tank
40-15-0201-028	965 Baltimore Pike	2008	W005426	wet system inspected
40-13-0128-002A	618 Whiskey Springs Road	2008	W005424	New Sand Mound for Malfunctioning Absorption Field
40-10-0632-004	1207 Rockledge Drive	2008	W005431	replace malfunctioning drainfield
40-11-0286-031A	744 Petersburg Road	2007	W005423	no malfunction to surface - would not pass real estate certification
40-08-0575-003	1450 Trindle Road	2007	W005422	connect new building to ex. System
40-40-2654-030	92 Victory Church Road	2007	W005421	new tank
40-14-0142-030	224 Oxford Road	2007	W005419	renewal of permit # R28715
40-10-0632-011	510 Adams Road	2007	W005417	New Sand Mound
40-31-2185-035	122 Mill Street	2007	W005416	new tank
40-09-0535-001S	531 South Middlesex Road	2007	W005415	Malfunctioning Sand Mound
40-12-0346-011	627 Gutshall Road	2007	W005408	Laterals clogged
40-10-0636-257	413 Heisers Lane	2007	W005407	New Sand Mound for Malfunctioning Absorption Field
40-11-0286-005	410 East Old York Road	2007	W005404	New Sand Mound
40-10-0636-257	413 Heisers Lane	2007	R28997	Same as W005407 above
40-38-2180-003	736 Baltimore Pike	2006	W005342	A/B system - never installed
40-37-2540-004	644 Baltimore Pike	2006	W005339	surface malfunction
40-41-2676-005	120 Frost Road	2006	W005338	eco-flo with at-grade bed (replaces ex. Bed)
40-11-0288-009	234 Old York Road	2006	W005322	new tank
40-12-0344-041	554 Mountain Road	2006	W005328	tank replacement
40-14-0142-026	783 Baltimore Pike	2006	W005327	New Sand Mound

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-10-0636-063	488 Petersburg Road	2006	W005326	New Sand Mound for Malfunctioning Absorption Field
40-40-2654-020	455 Oxford Road	2005	W005315	eco-flo with at-grade bed (replaces ex. Bed)
40-12-0342-006	59 Red Tank Road	2005	R28987	New Sand Mound for Malfunctioning Absorption Field
40-14-0140-039A	301 Whiskey Springs Road	2005	W005314	At-grade bed
40-12-0344-050	516 Mountain Road	2005	W005313	New tank
40-14-0140-015C	321 Whiskey Springs Road	2005	W005312	New Sand Mound for Malfunctioning Absorption Field
40-11-0286-028	729 Petersburg Road	2005	W005309	New Sand Mound for Malfunctioning Absorption Field
40-14-0140-015C	321 Whiskey Springs Road	2005	W005307	Malfunction
40-40-2652-005	191 Frost Road	2005	R28992	New Sand Mound for Malfunctioning Absorption Field
40-09-0529-029	1144 Rockledge Drive	2004	R28979	New Sand Mound for Malfunctioning Absorption Field
40-12-0344-016	534 Mountain Road	2004	R28975	new tank
40-11-0288-044	63 Ladnor Lane	2004	R28976	new tank
40-40-2656-013.-EX	960 Baltimore Pike	2004	R28969	New Sand Mound
40-23-0585-008	110 Hollenbaugh Road	2004	R28968	new tank
40-12-0342-026	149 Red Tank Road	2004	R28958	new tank install
40-24-0752-042	1423 Holly Pike	2004	R28965	replace filter and clogged stone in sand mound
40-10-0638-014	822 Ridge Road	2004	R28963	proposed lot
40-11-0288-057	15 Morrison Way	2003	R28960	Replace broken septic tank
40-12-0342-042	140 Cedar Street	2003	R28959	
40-12-0344-002A-EX	534 Park Drive	2003	R28957	Soil Testing for new lots
40-37-2545-010	29 Appalachian Trail Road	2003	R28749	Replace existing holding tank installation
40-38-2180-003	736 Baltimore Pike	2003	R28748	Replace septic tank
40-24-0746-004	1404 Walnut Bottom Road	2003	R28747	
40-10-0636-005	430 Petersburg Road	2003	R28746	New tank only
40-15-0199-012	501 Oxford Road	2003	R28674	New Sand Mound for Malfunctioning Absorption Field
40-11-0286-026	759 Petersburg Road	2003	R28745	New tank only
40-14-0142-030	224 Oxford Road	2003	R28715	Best technical guidance- Sand Mound
40-10-0634-017	1137 S. Spring Garden Street	2003	R28731	Replace tank & clogged pipe
40-10-0638-024	825 York Road	2003	R28737	New tank only
40-12-0342-045	100 Cedar Street	2003	R28729	New Sand Mound
40-39-2209-011	816 Baltimore Pike	2003	R28722	New Sand Mound
40-11-0288-004	150 E. Old York Road	2002	R28709	
40-43-2759-021	886 Goodyear Road	2002	R28706	New Sand Mound
40-15-0199-010A	221 Pine School Road	2002	R28696	Holding tank to replace cesspool
40-11-0290-009(B)	318 Pine Road	2002	R28704	New tank only
40-09-0533-134	518 S. Middlesex Road	2002	R28701	
40-12-0342-010	63 Red Tank Road	2002	R28700	replace tank

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-10-0636-038	402 Heisers Lane	2002	R28677	new tank only
40-12-0344-039-TR03819	564 Mountain Road	2002	R28683	new tank only
40-10-0636-040	597 Petersburg Road	2002	R28682	new tank only
40-12-0344-039	562 Mountain Road	2002	R28681	new tank only
40-14-0140-074	250 Whiskey Springs Road	2001	R28679	best technical guidance
40-23-0592-052	78 Fairview Street	2001	R28672	new tank only
40-09-0535-017	593 S. Middlesex Road	2001	R28656	existing bed full of sludge
40-23-0600-009	56 Rolling Drive	2001	R28671	Standard Trench
40-12-0340-019	724 W. Pine Street	2001	R28670	New Sand Mound
40-12-0344-010	655 Gutshall Road	2001	R28669	New Sand Mound
40-11-0288-003J	144 E. Old York Road	2001	R28667	Terralifting against SEO advice
40-11-0288-003J	144 E. Old York Road	2001	R28666	See Above
40-09-0533-011	531 York Road	2001	R28665	New Tank
40-10-0632-008	1503 Rockledge Drive	2001	R28662	No work performed - refund
40-11-0286-089	926 Petersburg Road	2001	R28659	
40-24-0744-023	14 Annendale Drive	2001	R28658	best technical guidance
40-11-0286-016	541 E. Old York Road	2001	R28657	replace tank only
40-23-0604-002	1226 Walnut Bottom Road	2001	R28652	new tank only
40-41-2676-010	125 Frost Road	2001	R28651	best technical guidance
40-37-2545-004	4685 Carlisle Road	2001	O52969	holding tank replacement
40-24-0744-035	6 Adams Road	2000	O53409	new tank only
40-25-0060-006	406 Petersburg Road	2000	O53406	
40-12-0340-029-EX	202 W. Butler Street	2000	O52959	tank replacement
40-10-0632-006	1538 Holly Pike	2000	O52957	Replace tank & New Sand Mound
40-10-0638-029A	842 York Road	2000	O52956	
40-24-0752-032	138 Bonnybrook Road	2000	O52955	
40-40-2654-026	99 Victory Church Road	2000	O52954	new tank only
40-24-0746-019	120 Garfield Drive	2000	O52953	
40-24-0752-035	104 Bonnybrook Road	2000	O52952	best technical guidance - replace tank & stone
40-31-2185-025A	307 Zion Road	2000	O52951	new tank only
40-23-0604-015	1224 Walnut Bottom Road	2000	O52950	new tank only/box/pump only
40-09-0531-017	390 Petersburg Road	2000	O53422	new tank only
40-09-0529-035	1130 Rockledge Drive	2000	O53420	replaced existing cracked septic tank
40-12-0342-025B	143 Red Tank Road	2000	O53414	New Sand Mound
40-40-2654-016	399 Oxford Road	2000	O53412	New Sand Mound - adjacent property easement
40-11-0286-015	702 Petersburg Road	2000	O53407	best technical guidance
40-24-0746-037	141 Emerson Drive	2000	O53411	best technical guidance

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-24-0746-017	77 Garfield Drive	2000	O53408	new tank only
40-15-0201-014	60 Smith Road	2000	O53405	Second home connect to system
40-11-0286-050	514 Hinkel Lane	2000	N48291	New Sand Mound for Malfunctioning Absorption Field
40-13-0128-006-EX	571 Mountain Road	2000	O53410	Clogged Sand Mound (system eventually replaced)
40-31-2185-025	309 Zion Road	2000	O53403	new septic tank only
40-10-0638-031	261 S. Ridge Road	2000	O52999	new septic tank only
40-11-0290-012	330 Pine Road	2000	O52990	best technical guidance
40-24-0746-027	150 Garfield Drive	2000	O52992	new tank/pump only
	65 Zion Road (NSN)	1999	O52989	septic tank replacement
	134 Bonnybrook Road (NSN)	1999	O52984	clogged pipe - roots
40-24-0744-026	2 Carlton Lace Circle	1999	O52982	best technical guidance - new tank & absorption field to replace trenches
40-43-2759-008.-EX	925 Goodyear Road	1999	O52981	connection
40-11-0288-012	160 E. Old York Road	1999	O53400	eco-flo with at-grade bed (replaces ex. Bed)
40-24-0744-047	25 Annendale Drive	1999	O52978	
40-14-0142-034A	116 Old Town Road	1999	O52873	best technical guidance
40-24-0746-011	1410 Webster Drive	1999	O52863	repair existing well 75' away. Best technical guidance; well could get polluted.
40-24-0746-044	1402 Viewmore Drive	1999	O52871	new tank
40-12-0344-016	534 Mountain Road	1999	O52870	
40-10-0638-005	661 S. Middlesex Road	1999	O52865	new tank only
40-25-0060-017	427 Petersburg Road	1998	O52861	new tank
40-13-0126-036	1150 Petersburg Road	1998	O52860	using all available area - no guarantees
40-10-0632-022	1610 Holly Pike	1998	O52858	New Sand Mound
40-10-0636-093	847 Lindsey Road	1998	O52857	
40-25-0060-012	403 Petersburg Road	1998	O52852	best technical guidance - no guarantees
40-24-0744-004	1601 Walnut Bottom Road	1998	N48899	
40-11-0286-004A	402 E. Old York Road	1998	N48896	new septic tank only
40-11-0288-010	231 E. Old York Road	1998	N48895	new tank only
40-24-0746-008	1460 Webster Drive	1998	N48883	existing bed full of sludge
40-11-0288-015	1794 Rockledge Drive	1998	N48893	keep existing drain field; replace damaged tank
40-24-0752-003	1310 Holly Pike	1998	N48891	
40-22-0489-161	313 James Road	1998	N48890	new tank
40-39-2211-021	10 Logan Drive	1998	N48887	New Sand Mound
40-13-0126-042	629 Whiskey Springs Road	1998	N48886	
	85 Zion Road (NSN)	1998	N48885	
40-11-0288-003D	95 Ladnor Lane	1998	N48884	new tank
40-10-0632-029	1578 Rockledge Drive	1998	N48881	New Sand Mound for Malfunctioning Absorption Field
40-40-2656-018	60 Victory Church Road	1997	N48232	new septic tanks only

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-09-0535-007	823 Lisburn Road	1997	N48879	
40-12-0344-016	534 Mountain Road	1997	N48877	
40-09-0535-001R	529 S. Middlesex Road	1997	N48876	absorption area disturbed during construction
40-24-0752-029	1249 Holly Pike	1997	N48292	
40-11-0286-023	614 Lerew Road	1997	N48290	New tank & distribution tank
40-11-0286-101	550 Park Drive	1997	N48289	Holding tank (now on public sewer)
40-24-0746-021	131 Emerson Drive	1997	N48284	best technical guidance - no guarantees.
40-10-0632-017	1582 Holly Pike	1997	N48283	best technical guidance - no guarantees.
40-39-2209-004	799 Baltimore Pike	1997	N48282	new tank only
40-11-0286-028	729 Petersburg Road	1997	N48276	no perc
40-23-0585-006	7 Hilltop Circle	1997	N48275	New Sand Mound
40-09-0535-001E	507 S. Middlesex Road	1997	N48249	
40-14-0140-039A	301 Whiskey Springs Road	1997	N48247	seepage bed overflowing into holding tanks
40-11-0286-001C	319 E. Old York Road	1997	N48236	new tank, replace old clogged pipe with new plastic pipe
40-10-0636-067	498 Petersburg Road	1997	N48238	repair existing system
40-37-2545-020	28 Appalachian Trail	1996	N48233	new septic tank only
40-24-0746-027	150 Garfield Drive	1996	N48228	
40-24-0752-010	1418 Holly Pike	1996	L67199	new 1500 gallon septic tank and new 4" plastic pipe
40-37-2545-016	14 Appalachian Trail Road	1996	L67198	install new 2 chambered 1000 gallon septic tank in place of old tank
40-11-0286-028	729 Petersburg Road	1996	L67197	new 1250 gallon tank (either 2 chambers or 2 tanks = 1250 gals)
40-22-0479-001	1152 Royer Road	1996	L67189	replace stone and pipe in existing system
	60 Zion Road	1996	L67187	
40-37-2540-006	650 Baltimore Pike	1996	L67186	install new 1250 gallon tank in place of 1000 gallon tank
40-39-2211-005	276 Oxford Road	1996	L67183	
40-38-2175-006	451 Old State Road	1996	L67181	new septic tank only
40-12-0344-037	568 Mountain Road	1996	L67180	Malfunction - Needs holding tank
40-09-0533-009A	152 Lisburn Road	1996	L67179	install a 2nd 1000 gallon septic tank only
40-39-2211-026	9 Logan Drive	1996	L67170	
40-39-2214-008	283 Frost Road	1996	L67165	replace old with new 1000 gallon tank & connect to existing system
40-37-2540-005A	649 Baltimore Pike	1995	L67161	repair due to unsuitable soil conditions, install holding tanks for existing house.
40-09-0535-005	150 Byers Road	1995	L67154	install new 1000 gallon tank in place of old 300 gallon tank
40-13-0218-001	599 Mountain Road	1995	L67153	install 400 gal. pump tank w/alarm & connect to existing septic system
40-23-0592-013	11 Wood Lane	1995	L67150	
40-14-0142-026B	779 Baltimore Pike	1995	L67149	
40-24-0752-014	1419 Holly Pike	1995	L67147	install new 1000 gallon septic tank only
40-09-0535-001B	1600 Trindle Road	1995	L67146	New Sand Mound
40-32-2334-073	513 Sandbank Road	1995	L67144	best technical guidance, no guarantees, system may fail

SUMMARY OF SEPTIC REPAIR PERMITS (1993-2010)

PIN	Site Address	Year	Permit #	Description of repair
40-24-0744-023	14 Annendale Drive	1995	L67143	new 1000 gallon septic tank
40-23-0592-005	8 Wood Lane	1995	L67140	
40-32-2334-006A	6 Maurice Road	1995	L67139	install 12" new stone and new 4" pipe. No guarantee will not fail.
40-25-0060-013	405 Petersburg Road	1995	L67137	replace existing broken pipe
40-11-0286-068	914 Petersburg Road	1995	L67129	Install pressure dosing bed
40-10-0636-032	641 Lindsey Road	1995	L67128	perc rate 130 mpi (unsuitable). Best technical guidance, no guarantee
40-10-0634-099	253 Bonnybrook Road	1995	N48875	Seepage beds installed
40-10-0634-055	322 Bonnybrook Road	1995	J43878	New Sand Mound for Malfunctioning Absorption Field
40-30-2644-003	232 Pine Road	1995	J43896	existing lines to be repaired
40-43-2759-015	885 Goodyear Road	1995	J43894	New tank & new bed
40-38-2180-004	744 Baltimore Pike	1995	J43881	install new 1000 gallon tank only
40-11-0288-004	150 E. Old York Road	1994	J43877	new tank
40-	711 Sand Bank Road (not in st. listing)	1994	J44324	new tank
40-24-0744-022	16 Annendale Drive	1994	J44320	
40-39-2211-005	276 Oxford Road	1994	J44314	new tank
40-28-2098-001	568 E. Old York Road	1994	J44313	replace absorption field
40-11-0284-023	373 Mountain Road	1994	J44312	
40-12-0344-045	533 Mountain Road	1994	L44589	replace existing privies
40-24-0744-010	1640 Walnut Bottom Road	1994	J44309	new tank
40-32-2332-048	100 Ian Drive	1994	J44303	
40-23-0585-004	154 Hollenbaugh Road	1994	J44302	New Sand Mound for Malfunctioning Absorption Field
40-43-2759-018	875 Goodyear Road	1994	L44599	new tank
40-12-0342-009	39 Red Tank Road	1994	L44597	replace lids on tanks; add extension risers
40-12-0344-119	70 Wise Lane	1994	L44591	new system - remove existing trailer
40-14-0142-036	100 Old Town Road	1993	L44582	New Sand Mound for Malfunctioning Absorption Field
40-	Hilltop Circle	1993	L44578	New Sand Mound for Malfunctioning Absorption Field
40-15-0199-013	181 Pine School Road	1993	L44577	New Sand Mound for Malfunctioning Absorption Field
40-23-0592-015	5 Wood Lane	1993	K49348	replace cesspool
40-	510 S. Baltimore Ave. (NSN)	1993	K49342	remove pump in dose tank; use tanks as holding tanks until sand mound repaired or replaced
40-09-0527-010B	716 Allen Road	1993	K49340	move existing tank
40-10-0632-001A	398 Adams Road	1993	K49336	repair collapsed pipe
40-40-11-0288-001	1698 Holly Pike	1993	K49333	replace absorption field with larger area
40-11-0286-055	552 Park Drive	1993	K49332	new tank
40-10-0638-023	831 York Road	1993	K49331	New in-ground
40-12-0344-053	60 Wise Lane	1993	K49329	replace absorption field with larger area
40-37-2545-009	25 Appalachian Trail Road	1993	K49328	malfunction inspection
40-32-2338-003	215 Zion Road	1993	K49322	trenches